



## IMSA PENALTY NOTICE

TP - 26 - 1



### ENTRY

99  
TCR

**TYPE:** Technical

**EVENT:** The Rolex 24 at Daytona

**SERIES:** IMPC

**TEAM:** Victor Gonzalez Racing

**ENTRANT:** Victor Gonzalez  
**REPRESENTATIVE:**

**DRIVER:**

**AFFECTED PARTY:** N/A

### INFRACTION

**OFFICIAL:** Gregory Rodgers

The Official listed above has reviewed the following matter and determined it to be a breach of the IMSA RULES committed by the Team and imposes the penalty(ies) listed below.

**DATE & TIME:** 1/22/2026 3:27:00 PM    **LOCATION:** Technical Inspection

**REGULATION:** 22.7 Technical Non-Compliance

**FACTS:** During post-Qualifying Technical Inspection, TCR Car #99 was found to have bodywork repairs in violation of TCR Technical Regulation 7.3.1

### PENALTY

**FINE:** N/A

**CHANGE:** Lap times are invalidated, Car is moved to the back of the Class.

**RETURN TROPHY**

### SIGNATURES

**Approved by:**



Matthew Kurdock

**Delivered by:**



Jeff Mishtawy

**Received by:**



Victor Gonzalez  
Victor Gonzalez Racing

1/22/2026 3:42:57 PM

1/22/2026 4:13:43 PM



## IMSA PENALTY NOTICE

TP - 26 - 1



### REGULATION # SR & SSR

TR 7.3.1. All servicing or repair must be made in good faith to restore the Car and all components to their originally intended form and function as defined by the Specification.

SR 22.7.1. (SSR) Cars out of compliance with the Technical specifications and/or regulations may be penalized by being moved to the back of class, or up to and including Removal from the results, and/or any penalty available per Art. 57.